



Readers are advised that all papers published in the *Welding Journal's* Research Supplement undergo Peer Review before publication for: 1) originality of the contribution; 2) technical value to the welding community; 3) prior publication of the material being reviewed; 4) proper credit to others working in the same area; and 5) justification of the conclusions based on the results.

The names of the more than 160 individuals serving on the AWS Peer Review Panel are published periodically. All are experts in their respective technical areas, and all are volunteers in the program.

Failure Investigation of Eddystone Main Steam Piping

Cause of through wall cracks in 316 stainless steel is established

BY J. F. DELONG, J. E. BYNUM, F. V. ELLIS, M. H. RAFIEE, W. F. SIDDALL, T. DAIKOKU AND H. HANEDA

ABSTRACT. In March 1983, personnel at Philadelphia Electric's Eddystone No. 1 power plant discovered a through wall leak in the main steam outlet piping. This pipe was designed to carry steam at a pressure of 5300 psi (36,538 kPa) and a temperature of 1210°F (654°C). The pipe was made of 316 stainless steel and had been operated approximately 130,000 hours at the time that failure was discovered. Subsequent inspection revealed

that many OD cracks existed in this piping system.

This paper details the investigation into the cause of the failure. The following elements are highlighted: the in-place metallography which successfully used the plastic replica technique; the elastic-plastic stress analysis and life prediction techniques carried out to assess probable failure modes and loadings; and the experimental stress analysis which was conducted to confirm analytical hypotheses.

Introduction

The discovery in March 1983 of extensive cracking in the main steam lines at Philadelphia Electric's Eddystone Unit No. 1 power plant led to a forced outage of the plant and the present failure investigation. This investigation was conducted by Philadelphia Electric Co. (PECO), Combustion Engineering, Inc., and Mitsubishi Heavy Industries, Ltd.

Eddystone Unit No. 1 commenced commercial operation on February 5, 1960. The plant was designed for turbine

conditions of 5000 psi (34,470 kPa) at 1200°F (649°C) temperature with two reheats to 1050°F (566°C). The turbine was rated at 325 MW. The unit is a coal fired, supercritical monotube design with a once through twin furnace manufactured by Combustion Engineering, Inc.

From the first startup to the discovery of the main steam line crack, the 316 stainless steel piping system accumulated 130,520 hours of high temperature operation. During this period, the unit experienced 326 startup cycles, many of which were due to forced shutdowns. The main steam line, including the welds, performed satisfactorily until the first indication of a problem in 1980. At that time, a small area of outside diameter cracking was discovered by visual examination near a hanger lug location. Immediately, one-third of the piping system, including all pipe sections from the same heat as the cracked section, was examined with dye penetrant. No other cracks were found. The cracked section was removed and high temperature stress rupture tests were performed on it. The rupture data was analyzed by parametric methods

Paper presented in a technical session sponsored by the Metal Properties Council at the 65th annual AWS Convention held April 9-13, 1984, in Dallas, Tex.

J. F. DELONG is senior metallurgical engineer, J. E. BYNUM is supervisor, elevated temperature testing, and F. V. ELLIS is principal research engineer with Philadelphia Electric Co., Philadelphia, Pa. M. H. RAFIEE is supervisor, metallography, CE Metallurgical & Materials Lab, Chattanooga, Tenn. W. F. SIDDALL is manager, engineering development, CE Fossil Power Systems, Windsor, Conn. T. DAIKOKU is manager, research laboratories, and H. HANEDA is manager, boiler development, for Mitsubishi Heavy Industries, Tokyo, Japan.



Fig. 5—Damage adjacent to main crack consisting of cavities and single grain facet (sgf) cracks (Unetched)

and scanning electron microscopy (SEM) techniques were used to examine sections of the failed pipe. In addition to the metallographic examination, tensile, creep, Charpy, and compact tension tests were performed.

Metallographic Examination

The longitudinal cracking on the outside of the failed pipe is shown in Fig. 1. A crack nearly through the wall and the surface appearance of the cracking are shown in Fig. 2. Figure 3 shows a transverse ring which has three major cracks.

The damage in all specimens examined



Fig. 6—Oriented cavitation in OD and midwall position while ID region is undamaged

was similar. At low magnification, intergranular oxide-filled cracks perpendicular to the hoop stress direction (Fig. 4) were found near the OD. Figure 5 shows single grain facet (sgf) cracks and grain boundary cavities in the region adjacent to the main crack. Use of a multiple etch polishing procedure (Ref. 8) facilitated detection of the cavities which occurred at grain boundaries oriented either normal or nearly normal to the hoop stress direction. This oriented cavitation is observed on the OD and midwall positions, but the inside diameter (ID) region is free of damage. The density variation of these cavities through the wall thickness is remarkably consistent from one circumferential location to another. Figure 6 shows this through wall variation at a circumferential position 90° from the major crack.

In every piece examined, the cracking starts at the OD or immediately beneath the surface, as shown in Fig. 3. It is presumed that the oriented cavities link

up and form the sgf cracks, which precede the major cracks and subsequent failure. Figure 7 shows the oriented cavities detected on the outside using a tangential section rather than the more common transverse sections. The combination of OD crack initiation and detection of oriented cavitation on tangential sections led to the use of plastic replica techniques for field inspection of the main steam line at the plant.

Examination at higher magnification revealed that the microstructure of the failed pipe consists of matrix precipitates (probably $M_{23}C_6$) and large sigma phase particles in the grain boundaries. Although decohesion at the sigma-austenite interface is cited as a potential failure mode for this sigma phase morphology, the cavitation found during this investigation occurs primarily in the ligament region between the sigma phase particles, as shown in Fig. 8.

It is possible to produce grain boundary fracture in the highly damaged micro-




Fig. 7—Oriented cavities on outside surface of pipe (50X)




Fig. 8—SEM photomicrograph showing grain boundary cavities in ligament between sigma phase particles




Fig. 13—Room temperature fracture face of 2B steam line material removed in 1980 at position near OD of pipe

Creep and Tensile Testing

A creep test on the 4B material ruptured in 270 hours at 1382°F (750°C) and 6.8 ksi (468.8 MPa). At the same conditions, the 2B material (Ref. 12) ruptured in 648 hours for a difference in log rupture time of 0.38. Both creep curves exhibited similar primary and secondary creep behavior up to strains of about 0.5%. Subsequently, the 4B material entered the tertiary creep stage accounting for the shorter rupture life.

Four circumferential tensile specimens were cut from the OD of the 4B steam line. The specimens had a 0.252 in. (6.4 mm) diameter, a 1 in. (25.4 mm) gage length and were tested at room temperature. The test results are listed in Table 2. The relatively low ductility values reflect the damaged condition of the material.

Fracture Testing

In order to assess the susceptibility of cracks to propagate rapidly in the steam lines, several fracture toughness tests were conducted. Charpy impact specimens and 1 in. (25.4 mm) thick compact tension specimens were cut from the

Table 2—Tensile Properties of 4B Steam Line from Eddystone Unit 1

Property	Specimen Code			
	DE-1	DE-2	DE-3	DE-4
Yield Strength (ksi)	44.1	42.9	42.8	44.1
Tensile Strength (ksi)	60.0	47.3	83.6	66.3
Elongation (%)			10.0	

Table 3—Charpy Impact Properties of 4B Steam Line from Eddystone Unit 1

Specimen Location	Test Temperature (°F)	Absorbed Energy (ft-lb)	Shear (%)	Lateral Expansion (mils)
OD	77	3	0	1
1/4t	77	4	0	1
3/4t	77	6	0	3
ID	77	23	5	18
OD	77	4	0	1
1/4t	77	6	0	4
3/4t	77	8	0	5
ID	77	24	5	21
OD	535	4	0	2
1/4t	535	9	0	10
3/4t	535	10	0	15
ID	535	38	99	39
OD	1150	5	0	6
1/4t	1150	7	0	7
3/4t	1150	10	0	11
ID	1150	36	100	41

steam line which contained several cracks. The specimens were positioned so their fracture planes and the crack planes had similar orientations.

The Charpy impact testing was performed in accordance with ASTM Standard Method E-23. The data, which are shown in Table 3, indicate a significant increase in toughness as the inside diameter is approached. This coincides with the radial damage distribution revealed by the metallography. Increasing the test temperature from 77° to 1150°F (25°C to 621°C) does increase the toughness somewhat, but not enough to indicate that any ductility or fracture mode transition takes place.

The compact tension specimens were prepared and tested in accordance with




Fig. 15—Grain boundary facet, sigma phase particles and sgf cracks on fracture surface for specimen shown in Fig. 14. Specimen was fractured at LN₂ temperature



Fig. 14—Collage of creep specimen from 2B steam line. Specimen fractured at 750°C (1382°F) and 47 MPa (6.8 ksi)



Fig. 16 - Comparison of microstructure revealed by OD plastic replication and metallographic mount of boat sample for the superheater outlet header. Left - replicating technique; center - direct viewing; right - transverse view

strated in Fig. 16 for one location. The other locations from which the boat samples were taken exhibited the same similarity.

Metallography Conclusions

From the tests conducted and the data collected, it was determined that the microstructure observed at the surface of the components was a representative structure and not merely a surface phenomenon. The material upstream of the boiler stop valve showed creep damage when sigma phase was present, and the material downstream of the boiler stop valve showed no creep damage, even in pipe sections which had a blocky sigma microstructure.

Failure Scenario

At this point in the failure investigation, we had established the following facts and observations:

1. Cracking started from the pipe OD and propagated axially along the pipe and radially through the wall thickness.
2. Cracks were intergranular.
3. Creep voids had opened in grain boundaries.
4. No cracks or creep voids were detected downstream of the boiler stop valves.
5. Ductility tests showed the outer two-thirds of the pipe wall to have low ductility.
6. The pipe showed no evidence of creep swelling.
7. Chemical analysis of the 316 stainless steel material indicated compliance with the original requirements of the specification.

Facts one, two and three taken together would indicate the classic case of creep rupture of a pressurized cylinder under internal pressure. In order to accept this failure scenario, one would have to conclude that: one, the material

was substandard, or two, the allowable stress in the ASME Code was very optimistic.

Fact seven established that the material was not substandard, but it should be noted that cracking did correlate with the weaker heats of material. Because of facts four, five, and six, we became convinced that we were not dealing with the classic case of stress rupture.

If this material was merely weak in creep, it would have swelled before it ruptured. The stress rupture conclusion also did not explain the fact that no cracking or creep voids had been found downstream of the boiler stop valves. It was these inconsistencies which forced us to abandon failure scenarios which assumed bad material or incorrect allowable stresses.

The fact that the failed pipe had not swelled and that a definite ductility gradient was present across the wall thickness directly led to the following speculations:

1. Residual stresses combined with primary stresses to cause premature failure.
2. Since a residual stress field must be self-equilibrating, the outer two-thirds of wall thickness must have been tensile and the inner third compressive.
3. The most likely source of this resid-

ual stress field is a severe thermal down-shock.

4. Since the material downstream of the stop valves appears undamaged, this down-shock must occur when the boiler stop valve is closed.

This failure theory was arrived at because it appeared to be the only hypothesis which was consistent with the facts and observations determined during the preliminary assessment phase of this investigation. In order to test the likelihood of this theory being correct, analytical studies were carried out using assumed thermal loadings. The objective of these studies were twofold: one, to numerically demonstrate that the failure scenario was in agreement with established mathematical laws and theories; and two, to assess the severity of thermal shock required to predict failure due to creep rupture in the known time frame.

Stress Analysis

A transient heat transfer and thermal stress analysis was performed for a forced cooldown of 500°F (278°C) in 5 minutes using the computer program, CREPLACYL. CREPLACYL is a CE program which calculates the plastic and creep strains induced in thick wall cylinders due to transient thermal and pressure load-




Fig. 17 - Thermal gradient main steam pipe - 500°F in 5 minutes down-shock transient

