

# Dress for success

## Manual Welder's Required PPE



Weld helmet

Cap (visor turned to Back) or welder's beanie

Ear Plugs

Industrial Quality Safety Glasses



Long sleeved welding cape (leather or saiken) OVER 100% Cotton shirt

Long sleeved welding jacket (leather or saiken)



Gauntlet Leather Welding Gloves




Natural fiber pants (100% cotton recommended) No cuffs or frays or holes



Spats are required on boots with laces.

Recommend metatarsal protectors

Hightop Leather Boots (Steel Toes)



# Dress for success

## Robot Welder's Required PPE

