Oxide before welding over

bearding

Unstable arc deflecting back & forth

Oxide after welding over