

### Overlap

Definition: When the face of the weld extends beyond the (point of fusion) toe of the weld. **Shall not be premitted.**

