
Training Performed By Date

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Monday, November 07, 2011</i>				
	McLaughlin, Brad	6010/7018 6" Sch 80 6G	16:00	22:00
	Coats, Mike	6010/7018 6" Sch 80 6G	16:00	22:00
	George, Johnny	6010/7018 6" Sch 80 6G	16:00	22:00
	Snider, Josh	6010/7018 6" Sch 80 6G	16:00	22:00
	McElwain, James	6010/7018 6" Sch 80 6G	16:00	22:00
	Strom, Steven	6010/7018 6" Sch 80 6G	16:00	22:00
<i>Tuesday, November 08, 2011</i>				
	McLaughlin, Brad	6010/7018 6" Sch 80 6G	16:00	22:00
	Lester, Cedric Jobias	6010/7018 6" Sch 80 6G	16:00	22:00
	Coats, Mike	6010/7018 6" Sch 80 6G	16:00	22:00
	George, Johnny	6010/7018 6" Sch 80 6G	16:00	22:00
	Hester, Michael	6010 Tee Vertical	16:00	22:00
	McElwain, James	6010/7018 6" Sch 80 6G	16:00	22:00
	Strom, Steven	6010/7018 6" Sch 80 6G	16:00	22:00
<i>Thursday, November 10, 2011</i>				
	Lester, Cedric Jobias	6010 Tee Vertical	16:00	17:00
	Lester, Cedric Jobias	7018 Tee Vertical	17:00	18:00
	Lester, Cedric Jobias	7018 Tee, Vertical, On Floor	18:00	18:20
	Lester, Cedric Jobias	6010/7018 2G, Open Root 3/8"	18:20	20:00
	Lester, Cedric Jobias	Basic Welding Related Terms	20:00	22:00
	Hester, Michael	6010 Tee Vertical	16:00	18:00
	Hester, Michael	7018 Tee Vertical	18:00	20:00
	Hester, Michael	Basic Welding Related Terms	20:00	22:00
	McElwain, James	6010 Tee Vertical	16:00	18:00
	McElwain, James	7018 Tee Vertical	18:00	20:00
	McElwain, James	Basic Welding Related Terms	20:00	22:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Monday, November 14, 2011</i>				
	McLaughlin, Brad	6010 Tee Vertical	17:00	18:00
	McLaughlin, Brad	7018 Tee Vertical	18:00	19:00
	McLaughlin, Brad	7018 Pad Vertical	19:00	19:30
	Coats, Mike	6010 Tee Vertical	16:30	18:00
	Coats, Mike	7018 Tee Vertical	18:00	19:00
	Coats, Mike	7018 Pad Vertical	19:00	19:30
	Coats, Mike	Basic Welding Related Terms	19:30	20:30
	Coats, Mike	7018 Tee Vertical	20:30	20:45
	George, Johnny	6010 Tee Vertical	16:30	18:00
	George, Johnny	7018 Tee Vertical	18:00	19:00
	George, Johnny	7018 Pad Vertical	19:00	19:30
	George, Johnny	Basic Welding Related Terms	19:30	20:30
	George, Johnny	6010 Pad Weld Flat	20:30	21:15
	Snider, Josh	6010 Tee Vertical	17:15	18:00
	Snider, Josh	7018 Tee Vertical	18:00	19:00
	Snider, Josh	7018 Pad Vertical	19:00	19:30
	Snider, Josh	Basic Welding Related Terms	19:30	20:30
	Snider, Josh	7018 Tee Vertical	20:30	21:15
	McElwain, James	6010 Tee Vertical	17:00	18:00
	McElwain, James	7018 Tee Vertical	18:00	19:00
	McElwain, James	7018 Pad Vertical	19:00	19:30
	McElwain, James	Basic Welding Related Terms	19:30	20:30
	McElwain, James	6010 Tee Vertical	20:30	21:15
	McElwain, James	7018 Tee Vertical	21:15	22:00
	Strom, Steven	Absent	16:30	19:30

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, November 15, 2011</i>				
	McLaughlin, Brad	7018 Pad Vertical	18:00	19:45
	Lester, Cedric Jobias	Absent	16:30	19:30
	Coats, Mike	6010 Tee Vertical	17:30	18:00
	Coats, Mike	7018 Tee Vertical	18:00	22:00
	George, Johnny	6010 Tee Vertical	16:30	17:00
	George, Johnny	6010 Tee Vertical	17:00	17:30
	George, Johnny	6010 Pad Weld Vertical.	17:30	19:15
	Snider, Josh	6010 Tee Vertical	16:30	16:45
	Snider, Josh	7018 Tee Vertical	16:45	17:00
	Snider, Josh	7018 Pad Flat	17:00	19:00
	Snider, Josh	7018 Pad Horiz	19:00	20:15
	Hester, Michael	6010 Tee Vertical	16:30	17:00
	Hester, Michael	7018 Tee Vertical	17:00	21:30
	McElwain, James	6010 Tee Vertical	16:35	17:00
	McElwain, James	7018 Tee Vertical	17:00	18:30
	McElwain, James	7018 Tee Overhead	18:30	19:00
	McElwain, James	6010 Butt Square Groove Open Root 3/16" Vertical	19:00	20:30
	McElwain, James	6010 Butt Square Groove Open Root 3/16" Overhead	20:30	21:30
	Strom, Steven	6010 Tee Vertical	17:00	17:30
	Strom, Steven	7018 Tee Vertical	17:00	17:45
	Strom, Steven	7018 Tee Vertical	17:30	22:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Thursday, November 17, 2011</i>				
	McLaughlin, Brad	6010 Tee Vertical	18:00	20:00
	McLaughlin, Brad	Basic Welding Related Terms	20:00	21:00
	McLaughlin, Brad	6010 Tee Vertical	21:00	22:00
	Lester, Cedric Jobias	Absent	16:30	19:30
	Coats, Mike	7018 Tee Vertical	17:30	20:00
	Coats, Mike	Basic Welding Related Terms	20:00	21:00
	Coats, Mike	7018 Tee Vertical	21:00	22:00
	George, Johnny	6010 Tee Vertical	16:30	19:30
	Snider, Josh	Absent	16:30	19:30
	Hester, Michael	7018 Tee Vertical	16:30	20:00
	Hester, Michael	Basic Welding Related Terms	20:00	21:00
	Hester, Michael	7018 Tee Vertical	21:00	21:45
	McElwain, James	7018 Tee Vertical	16:30	17:10
	McElwain, James	6010 Butt Square Groove Open Root 3/16" Vertical	17:10	17:45
	McElwain, James	6010 Butt Square Groove Open Root 3/16" Overhead	17:45	18:10
	McElwain, James	6010 Butt Square Groove Open Root 3/16" Vertical	18:10	19:00
	McElwain, James	6010/7018 3G, Open Root 3/8"	19:00	20:00
	McElwain, James	Basic Welding Related Terms	20:00	21:00
	McElwain, James	6010/7018 3G, Open Root 3/8"	21:00	21:30
	Strom, Steven	7018 Tee Vertical	17:00	18:30
	Strom, Steven	6010 Tee Vertical	18:30	19:15
	Strom, Steven	6010 Butt Square Groove Open Root 3/16" Vertical	19:15	22:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Monday, November 21, 2011</i>				
	Lester, Cedric Jobias	7018 Tee Vertical	17:15	19:30
	Lester, Cedric Jobias	Safety Features with Oxyfuel Equipment	19:45	20:00
	Lester, Cedric Jobias	Basic Theory of Oxyfuel Setup and Cutting	20:00	20:45
	Lester, Cedric Jobias	6010 Butt Square Groove Open Root 3/16" Vertical	20:45	21:30
	Coats, Mike	7018 Tee Vertical	16:45	19:45
	Coats, Mike	Safety Features with Oxyfuel Equipment	19:45	20:00
	Coats, Mike	Basic Theory of Oxyfuel Setup and Cutting	20:00	20:45
	Coats, Mike	6010 Tee Vertical	20:45	21:30
	George, Johnny	7018 Tee Vertical	16:30	19:45
	George, Johnny	Safety Features with Oxyfuel Equipment	19:45	20:00
	George, Johnny	Basic Theory of Oxyfuel Setup and Cutting	20:00	20:45
	George, Johnny	7018 Tee Vertical	20:45	21:30
	Hester, Michael	7018 Tee Vertical	16:30	19:30
	Hester, Michael	Safety Features with Oxyfuel Equipment	19:45	20:00
	Hester, Michael	Basic Theory of Oxyfuel Setup and Cutting	20:00	20:45
	Hester, Michael	7018 Tee Vertical	20:45	21:30
	McElwain, James	7018 Tee Vertical	16:45	17:15
	McElwain, James	6010 Butt Square Groove Open Root 3/16" Vertical	17:15	17:45
	McElwain, James	6010/7018 3G, Open Root 3/8"	17:45	19:45
	McElwain, James	6010/7018 3G, Open Root 3/8"	17:45	19:45
	McElwain, James	Safety Features with Oxyfuel Equipment	19:45	20:00
	McElwain, James	Basic Theory of Oxyfuel Setup and Cutting	20:00	20:45
	McElwain, James	6010/7018 3G, Open Root 3/8"	20:45	21:30
	Strom, Steven	7018 Tee Vertical	16:30	17:00
	Strom, Steven	6010 Butt Square Groove Open Root 3/16" Vertical	17:00	18:00
	Strom, Steven	6010 Butt Square Groove Open Root 3/16" Horizontal	18:00	19:45
	Strom, Steven	Safety Features with Oxyfuel Equipment	19:45	20:00
	Strom, Steven	Basic Theory of Oxyfuel Setup and Cutting	20:00	20:45
	Strom, Steven	6010 Butt Square Groove Open Root 3/16" Vertical	20:45	22:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
-------------	----------------	------------------	--------------	-------------

Tuesday, November 22, 2011

Lester, Cedric Jobias	7018 Tee Vertical	16:30	16:45
Lester, Cedric Jobias	6010 Butt Square Groove Open Root 3/16" Vertical	16:45	20:00
Lester, Cedric Jobias	Basic Welding Related Terms	20:00	21:00
Coats, Mike	6010 Tee Vertical	17:00	17:45
Coats, Mike	7018 Tee Vertical	17:45	19:30
Coats, Mike	7018 Tee Overhead	19:30	20:00
Coats, Mike	Basic Welding Related Terms	20:00	21:00
Coats, Mike	7018 Tee Overhead	21:00	21:30
George, Johnny	7018 Tee Vertical	16:30	19:30
Hester, Michael	7018 Tee Vertical	16:30	16:45
Hester, Michael	7018 Tee Vertical	16:45	20:00
Hester, Michael	Basic Welding Related Terms	20:00	21:00
Hester, Michael	7018 Tee Vertical	21:00	21:45
McElwain, James	7018 Tee Vertical	17:00	17:30
McElwain, James	6010 Butt Square Groove Open Root 3/16" Vertical	17:30	18:00
McElwain, James	6010/7018 3G, Open Root 3/8"	18:00	20:00
McElwain, James	Basic Welding Related Terms	20:00	21:00
Strom, Steven	7018 Tee Vertical	17:00	17:30
Strom, Steven	6010 Butt Square Groove Open Root 3/16" Vertical	17:30	18:00
Strom, Steven	6010 Butt Square Groove Open Root 3/16" Horizontal	18:00	19:45
Strom, Steven	6010 Butt Square Groove Open Root 3/16" Overhead	19:45	20:00
Strom, Steven	Basic Welding Related Terms	20:00	21:00
Strom, Steven	6010 Butt Square Groove Open Root 3/16" Overhead	21:00	21:45

Friday, November 25, 2011

Hester, Michael	7018 Tee Vertical	16:15	18:30
Hester, Michael	7018 Tee Overhead	18:30	19:00
Strom, Steven	7018 Tee Vertical	16:30	16:45
Strom, Steven	6010 Butt Square Groove Open Root 3/16" Overhead	16:45	17:00
Strom, Steven	6010/7018 3G, Open Root 3/8"	17:00	19:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Monday, November 28, 2011</i>				
	McLaughlin, Brad	7018 Tee Vertical	18:00	19:00
	McLaughlin, Brad	Basic Welding Related Terms	19:00	20:00
	McLaughlin, Brad	7018 Tee Vertical	20:00	21:00
	Lester, Cedric Jobias	7018 Tee Vertical	17:15	17:30
	Lester, Cedric Jobias	6010 Butt Square Groove Open Root 3/16" Vertical	17:30	19:00
	Lester, Cedric Jobias	Basic Welding Related Terms	19:00	20:00
	Lester, Cedric Jobias	6010/7018 3G, Open Root 3/8"	20:00	21:15
	Coats, Mike	7018 Tee Vertical	16:30	17:00
	Coats, Mike	7018 Tee Overhead	17:00	18:30
	Coats, Mike	6010 Butt Square Groove Open Root 3/16" Vertical	18:30	19:00
	Coats, Mike	Basic Welding Related Terms	19:00	20:00
	George, Johnny	7018 Tee Vertical	16:30	18:00
	George, Johnny	6010 Butt Square Groove Open Root 3/16" Vertical	18:00	19:15
	Snider, Josh	7018 Tee Vertical	16:53	17:45
	Snider, Josh	7018 Tee Overhead	17:45	18:15
	Snider, Josh	6010 Butt Square Groove Open Root 3/16" Vertical	18:15	19:00
	Snider, Josh	Basic Welding Related Terms	19:00	20:00
	Snider, Josh	6010 Butt Square Groove Open Root 3/16" Vertical	20:00	20:40
	Hester, Michael	7018 Tee Vertical	16:15	17:15
	Hester, Michael	7018 Tee Overhead	17:15	18:15
	Hester, Michael	6010 Butt Square Groove Open Root 3/16" Vertical	18:15	19:00
	Hester, Michael	Basic Welding Related Terms	19:00	20:00
	Hester, Michael	7018 Tee Vertical	20:00	21:15
	McElwain, James	7018 Tee Vertical	17:00	17:30
	McElwain, James	6010 Butt Square Groove Open Root 3/16" Vertical	17:30	18:00
	McElwain, James	6010/7018 3G, Open Root 3/8"	18:00	19:00
	McElwain, James	Basic Welding Related Terms	19:00	20:00
	McElwain, James	6010/7018 3G, Open Root 3/8"	20:00	21:30
	Strom, Steven	7018 Tee Vertical	16:30	16:50
	Strom, Steven	6010 Butt Square Groove Open Root 3/16" Vertical	16:50	17:05
	Strom, Steven	6010/7018 3G, Open Root 3/8"	17:05	19:00
	Strom, Steven	Basic Welding Related Terms	19:00	20:00
	Strom, Steven	6010/7018 3G, Open Root 3/8"	20:00	21:30

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, November 29, 2011</i>				
	McLaughlin, Brad	7018 Tee Vertical	17:30	20:00
	McLaughlin, Brad	Basic Welding Related Terms	20:00	21:00
	Lester, Cedric Jobias	6010 Butt Square Groove Open Root 3/16" Vertical	18:00	19:00
	Lester, Cedric Jobias	6010/7018 3G, Open Root 3/8"	19:00	20:00
	Lester, Cedric Jobias	Basic Welding Related Terms	20:00	21:00
	Coats, Mike	7018 Tee Vertical	16:30	19:00
	Coats, Mike	7018 Tee Overhead	19:00	20:00
	Coats, Mike	Basic Welding Related Terms	20:00	21:00
	George, Johnny	7018 Tee Vertical	16:30	20:00
	George, Johnny	Basic Welding Related Terms	20:00	21:00
	Snider, Josh	7018 Tee Overhead	17:55	18:15
	Snider, Josh	6010 Butt Square Groove Open Root 3/16" Vertical	18:15	19:00
	Snider, Josh	6010 Butt Square Groove Open Root 3/16" Vertical	19:00	20:00
	Snider, Josh	Basic Welding Related Terms	20:00	21:00
	McElwain, James	7018 Tee Vertical	17:05	17:15
	McElwain, James	6010 Butt Square Groove Open Root 3/16" Vertical	17:15	20:00
	McElwain, James	Basic Welding Related Terms	20:00	21:00
	Strom, Steven	7018 Tee Vertical	16:45	17:00
	Strom, Steven	6010 Butt Square Groove Open Root 3/16" Vertical	17:00	17:30
	Strom, Steven	6010 Butt Square Groove Open Root 3/16" Vertical	17:15	17:30
	Strom, Steven	6010/7018 3G, Open Root 3/8"	17:30	19:45
	Strom, Steven	6010/7018 3G, Open Root 3/8"	17:30	20:00
	Strom, Steven	Basic Welding Related Terms	20:00	21:00
	Strom, Steven	6010/7018 3G, Open Root 3/8"	21:00	22:00

Thursday, December 01, 2011

	McLaughlin, Brad	7018 Tee Vertical	18:00	21:00
	Lester, Cedric Jobias	6010/7018 3G, Open Root 3/8"	17:45	19:30
	Lester, Cedric Jobias	6010/7018 4G, Open Root 3/8"	19:30	20:00
	Coats, Mike	7018 Tee Vertical	16:30	16:50
	Coats, Mike	7018 Tee Overhead	16:50	17:20
	Coats, Mike	6010 Butt Square Groove Open Root 3/16" Vertical	17:20	20:00
	Coats, Mike	6010 Butt Square Groove Open Root 3/16" Overhead	20:00	21:00
	George, Johnny	7018 Tee Vertical	17:00	19:30
	Snider, Josh	7018 Tee Vertical	17:00	18:02
	Strom, Steven	7018 Tee Vertical	17:00	17:15

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Monday, December 05, 2011</i>				
	McLaughlin, Brad	7018 Tee Vertical	17:00	21:00
	Coats, Mike	7018 Tee Vertical	16:30	17:30
	Coats, Mike	7018 Tee Overhead	17:30	21:00
	Snider, Josh	7018 Tee Vertical	16:30	19:30
	Hester, Michael	7018 Tee Vertical	16:30	21:00
	McElwain, James	7018 Tee Vertical	17:00	17:15
	McElwain, James	6010/7018 3G, Open Root 3/8"	17:15	21:00
	Strom, Steven	7018 Tee Vertical	16:30	17:00
	Strom, Steven	6010 Butt Square Groove Open Root 3/16" Vertical	17:00	19:00
	Strom, Steven	6010/7018 3G, Open Root 3/8"	19:00	22:00
<i>Tuesday, December 06, 2011</i>				
	McLaughlin, Brad	7018 Tee Vertical	17:00	21:00
	Coats, Mike	7018 Tee Vertical	16:30	17:30
	Coats, Mike	7018 Tee Overhead	17:30	21:00
	Snider, Josh	7018 Tee Vertical	16:30	19:30
	Hester, Michael	7018 Tee Vertical	16:30	21:00
	McElwain, James	7018 Tee Vertical	17:00	17:15
	McElwain, James	6010/7018 3G, Open Root 3/8"	17:15	19:00
	Strom, Steven	7018 Tee Vertical	16:30	17:00
	Strom, Steven	6010/7018 3G, Open Root 3/8"	17:00	19:00
	Strom, Steven	6010 Pad Weld Pipe Horiz	19:00	22:00
<i>Monday, December 12, 2011</i>				
	Coats, Mike	7018 Tee Vertical	17:00	18:00
	Coats, Mike	7018 Tee Overhead	18:00	19:00
	Coats, Mike	6010 Butt Square Groove Open Root 3/16" Vertical	19:00	19:45
	Snider, Josh	7018 Tee Vertical	16:35	20:20
	Hester, Michael	6010 Pad Weld Pipe Horiz	16:30	21:00
	McElwain, James	6010/7018 6" Sch 80 5G	16:30	20:07
	Strom, Steven	6010/7018 6" Sch 80 5G	17:00	21:30
<i>Tuesday, December 13, 2011</i>				
	Lester, Cedric Jobias	7018, Simulated Groove Weld with Flat Bars, overhead	17:00	21:10
	Lester, Cedric Jobias	7018, Simulated Groove Weld with Flat Bars, overhead	17:00	17:30
	Lester, Cedric Jobias	7018, Simulated Groove Weld with Flat Bars, Vertical	17:30	21:00
	Coats, Mike	7018, Simulated Groove Weld with Flat Bars, Vertical	17:00	20:30
	Snider, Josh	7018, Simulated Groove Weld with Flat Bars, Vertical	17:15	20:55
	Hester, Michael	7018, Simulated Groove Weld with Flat Bars, Vertical	16:30	20:00
	Hester, Michael	6010 Pad Weld Pipe Horiz	20:00	21:00
	McElwain, James	7018, Simulated Groove Weld with Flat Bars, overhead	16:30	21:00
	Strom, Steven	7018, Simulated Groove Weld with Flat Bars, overhead	17:00	21:15

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Thursday, December 15, 2011</i>				
	Lester, Cedric Jobias	7018, Simulated Groove Weld with Flat Bars, overhead	17:00	21:10
	Coats, Mike	7018, Simulated Groove Weld with Flat Bars, Vertical	17:30	19:00
	Coats, Mike	Test 7018 3G	19:00	20:00
	Snider, Josh	7018, Simulated Groove Weld with Flat Bars, Vertical	17:30	21:10
	Hester, Michael	7018, Simulated Groove Weld with Flat Bars, Vertical	16:30	19:00
	Hester, Michael	7018, Simulated Groove Weld with Flat Bars, Vertical	16:30	19:00
	Hester, Michael	Test 7018 3G	19:00	20:00
	Hester, Michael	Test 7018 3G	19:00	21:00
	McElwain, James	Simulated 5F Pipe	17:30	19:00
	McElwain, James	Simulated 6F Pipe	19:00	21:00
	Strom, Steven	7018, Simulated Groove Weld with Flat Bars, Vertical	16:30	21:15
<i>Monday, December 19, 2011</i>				
	Lester, Cedric Jobias	7018, Simulated Groove Weld with Flat Bars, overhead	17:01	19:45
	Lester, Cedric Jobias	Test 7018 4G	19:45	21:00
	Coats, Mike	Test 7018 3G	16:45	20:00
	Hester, Michael	Test 7018 3G	16:30	20:00
	McElwain, James	Simulated 5F Pipe	17:05	19:00
<i>Tuesday, December 20, 2011</i>				
	Coats, Mike	6010 Butt Square Groove Open Root 3/16" Vertical	17:00	18:30
	Coats, Mike	6010/7018 3G, Open Root 3/8"	18:30	20:30
	Hester, Michael	6010 Butt Square Groove Open Root 3/16" Vertical	16:30	18:30
	Hester, Michael	6010/7018 3G, Open Root 3/8"	18:30	20:30
<i>Thursday, December 22, 2011</i>				
	Coats, Mike	6010 Butt Square Groove Open Root 3/16" Vertical	16:30	17:15
	Coats, Mike	6010/7018 3G, Open Root 3/8"	17:15	19:45
	Hester, Michael	6010 Butt Square Groove Open Root 3/16" Vertical	16:30	17:45
	Hester, Michael	6010/7018 3G, Open Root 3/8"	17:45	20:30
	Clark, Zach	7018 Tee Vertical	17:00	17:15
	Clark, Zach	6010 Butt Square Groove Open Root 3/16" Vertical	17:15	17:40
	Clark, Zach	6010 Butt Square Groove Open Root 3/16" Overhead	17:40	18:00
	Clark, Zach	6010/7018 3G, Open Root 3/8"	18:00	19:20

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Monday, December 26, 2011</i>				
	Coats, Mike	7018 Tee Horiz	16:30	18:30
	Hester, Michael	6010/7018 3G, Open Root 3/8"	16:30	19:00
	Hester, Michael	Simulated 2F Pipe	19:00	20:00
	McElwain, James	Simulated 5F Pipe	18:00	19:30
	McElwain, James	6010/7018 6" Sch 80 2G	19:30	21:30
	Strom, Steven	6010/7018 4G, Open Root 3/8"	16:30	19:30
	Strom, Steven	6010/7018 6" Sch 80 2G	19:30	21:00
	Clark, Zach	6010/7018 3G, Open Root 3/8"	16:30	18:00
	Clark, Zach	Simulated 5F Pipe	18:00	19:00
	Clark, Zach	6010/7018 6" Sch 80 5G	19:00	20:00
	Ervin, Caleb	6010 Pad Weld Flat	17:22	21:30
<i>Tuesday, December 27, 2011</i>				
	Coats, Mike	Simulated 2F Pipe	17:00	20:00
	Hester, Michael	Simulated 2F Pipe	16:30	18:30
	Hester, Michael	Simulated 5F Pipe	18:30	21:00
	McElwain, James	6010/7018 6" Sch 80 2G	17:00	21:00
	Strom, Steven	6010/7018 6" Sch 80 2G	16:30	22:00
	Clark, Zach	6010/7018 6" Sch 80 5G	16:30	20:30
	Clark, Zeif	6010 Pad Weld Flat	16:30	20:30
<i>Thursday, December 29, 2011</i>				
	Hester, Michael	Simulated 5F Pipe	16:30	19:00
	Hester, Michael	7018 Tee Vertical	19:00	19:45
	Hester, Michael	6010 Butt Square Groove Open Root 3/16" Overhead	19:45	20:15
	Hester, Michael	6010/7018 4G, Open Root 3/8"	20:15	21:15
	McElwain, James	6010/7018 6" Sch 80 2G	16:45	19:00
	Strom, Steven	6010/7018 6" Sch 80 2G	16:45	21:15
	Clark, Zach	6010/7018 6" Sch 80 5G	17:00	19:00
	Clark, Zach	6010/7018 4G, Open Root 3/8"	19:00	20:45
<i>Tuesday, January 03, 2012</i>				
	Coats, Mike	6010 Butt Square Groove Open Root 3/16" Overhead	16:30	19:00
	Snider, Josh	7018 Tee Overhead	16:45	19:15
	Hester, Michael	Simulated 2F Pipe	16:30	20:00
	McElwain, James	6010/7018 6" Sch 80 2G	17:15	20:00
	Strom, Steven	6010/7018 2G, Open Root 3/8"	17:15	19:15
	Strom, Steven	6010/7018 6" Sch 80 2G	19:15	22:00
	Clark, Zach	6010/7018 6" Sch 80 5G	16:30	20:00
	Clark, Zach	6010/7018 4G, Open Root 3/8"	20:00	22:00
	Ervin, Caleb	6010 Pad Weld Flat	16:30	20:10

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Thursday, January 05, 2012</i>				
	Lester, Cedric Jobias	Simulated 2F Pipe	17:00	19:00
	Lester, Cedric Jobias	Safety Issues	19:00	20:00
	Lester, Cedric Jobias	Simulated 5F Pipe	20:00	21:10
	Coats, Mike	6010/7018 3G, Open Root 3/8"	16:45	18:00
	Coats, Mike	6010/7018 4G, Open Root 3/8"	18:00	19:00
	Coats, Mike	Safety Issues	19:00	20:00
	Coats, Mike	6010/7018 4G, Open Root 3/8"	20:00	20:15
	Hester, Michael	Simulated 2F Pipe	16:30	19:00
	Hester, Michael	Safety Issues	19:00	20:00
	Hester, Michael	Simulated 2F Pipe	20:00	21:15
	McElwain, James	6010/7018 6" Sch 80 2G	17:00	19:00
	McElwain, James	Safety Issues	19:00	20:00
	McElwain, James	6010/7018 6" Sch 80 2G	20:00	20:15
	Strom, Steven	6010/7018 6" Sch 80 2G	17:00	19:00
	Strom, Steven	Safety Issues	19:00	20:00
	Strom, Steven	6010/7018 6" Sch 80 2G	20:00	21:30
	Clark, Zach	6010/7018 6" Sch 80 5G	16:30	19:00
	Clark, Zach	Safety Issues	19:00	20:00
	Clark, Zach	6010/7018 6" Sch 80 5G	20:00	21:15
	Ervin, Caleb	6010 Pad Weld Flat	16:30	19:00
<i>Monday, January 09, 2012</i>				
	McLaughlin, Brad	7018 Tee Vertical	18:00	21:00
	Coats, Mike	6010/7018 4G, Open Root 3/8"	17:30	20:00
	Snider, Josh	7018 Pad Vertical	17:10	21:00
	Hester, Michael	Simulated 5F Pipe	16:30	21:00
	McElwain, James	6010/7018 6" Sch 80 2G	16:30	20:00
	Strom, Steven	6010/7018 6" Sch 80 2G	16:30	19:45
	Clark, Zach	6010/7018 6" Sch 80 5G	16:30	21:00
<i>Tuesday, January 10, 2012</i>				
	McLaughlin, Brad	7018 Tee Vertical	18:00	21:00
	Snider, Josh	7018, Simulated Groove Weld with Flat Bars, overhead	17:10	21:00
	Hester, Michael	Simulated 5F Pipe	16:30	21:00
	McElwain, James	6010/7018 6" Sch 80 2G	16:50	20:40
	Clark, Zach	6010/7018 6" Sch 80 5G	16:30	20:00
	Clark, Zach	6010/7018 6" Sch 80 5G	17:00	20:30
	Ervin, Caleb	6010 Pad Weld Flat	16:40	19:40

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Thursday, January 12, 2012</i>				
	McLaughlin, Brad	7018 Tee Vertical	18:00	20:00
	Snider, Josh	7018 Tee Vertical	18:20	20:00
	Hester, Michael	Simulated 5F Pipe	16:30	20:05
	Strom, Steven	6010/7018 6" Sch 80 2G	17:30	20:00
	Clark, Zach	6010/7018 6" Sch 80 5G	16:30	20:00
	Ervin, Caleb	6010 Pad Weld Horiz	16:30	20:15
<i>Monday, January 16, 2012</i>				
	McLaughlin, Brad	7018 Tee Vertical	18:00	21:00
	Lester, Cedric Jobias	Simulated 5F Pipe	17:00	21:00
	Coats, Mike	6010/7018 4G, Open Root 3/8"	16:30	20:00
	Snider, Josh	7018 Tee Vertical	17:00	20:00
	McElwain, James	6010/7018 6" Sch 80 2G	17:30	21:00
	Strom, Steven	6010/7018 6" Sch 80 2G	17:30	21:00
	Clark, Zach	6010/7018 6" Sch 80 5G	16:30	21:00
<i>Tuesday, January 17, 2012</i>				
	McLaughlin, Brad	Absent	16:30	21:00
	Lester, Cedric Jobias	FCAW 7 Vertical 3G	17:00	20:20
	Coats, Mike	7018, Simulated Groove Weld with Flat Bars, overhead	17:00	20:00
	Hester, Michael	6010 Butt Square Groove Open Root 3/16" Overhead	16:30	17:00
	Hester, Michael	7018, Simulated Groove Weld with Flat Bars, overhead	17:00	19:30
	Strom, Steven	6010/7018 6" Sch 80 2G	17:30	21:00
	Clark, Zach	6010/7018 6" Sch 80 5G	16:30	17:00
	Ervin, Caleb	6010 Pad Weld Vertical.	17:00	19:30
<i>Thursday, January 19, 2012</i>				
	Lester, Cedric Jobias	6010 Butt Square Groove Open Root 3/16" Horizontal	16:30	21:00
	Coats, Mike	7018, Simulated Groove Weld with Flat Bars, overhead	16:30	20:30
	Hester, Michael	7018, Simulated Groove Weld with Flat Bars, overhead	16:30	21:00
	McElwain, James	6010/7018 6" Sch 80 2G	16:45	21:00
	Strom, Steven	6010/7018 6" Sch 80 2G	17:30	19:30
	Strom, Steven	6010/7018 6" Sch 80 5G	19:30	21:00
	Clark, Zach	6010/7018 6" Sch 80 2G	16:30	17:00
	Clark, Zach	6010/7018 6" Sch 80 5G	16:30	20:30
	Ervin, Caleb	6010 Pad Weld Vertical.	17:30	18:45
	Ervin, Caleb	6010 Tee Horiz	18:45	20:00
<i>Monday, January 23, 2012</i>				
	McLaughlin, Brad	7018 Tee Vertical	18:00	21:00
	Coats, Mike	7018, Simulated Groove Weld with Flat Bars, overhead	17:00	20:00
	McElwain, James	6010/7018 6" Sch 80 5G	16:30	20:00
	Clark, Zach	6010/7018 6" Sch 80 2G	17:00	21:00
	Ervin, Caleb	6010 Tee Horiz	18:00	19:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, January 24, 2012</i>				
	McLaughlin, Brad	7018 Tee Vertical	18:00	21:00
	Coats, Mike	6010/7018 4G, Open Root 3/8"	17:00	20:00
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	21:00
	McElwain, James	6010/7018 6" Sch 80 5G	16:30	20:00
	Strom, Steven	6010/7018 6" Sch 80 5G	17:00	21:00
	Ervin, Caleb	6010 Tee Horiz	18:00	19:00
<i>Thursday, January 26, 2012</i>				
	McLaughlin, Brad	7018 Tee Vertical	17:20	18:00
	Coats, Mike	6010/7018 4G, Open Root 3/8"	17:00	19:50
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	21:00
	McElwain, James	6010/7018 6" Sch 80 5G	16:30	20:00
	Strom, Steven	6010/7018 6" Sch 80 5G	17:00	21:00
	Clark, Zach	6010/7018 6" Sch 80 2G	18:00	21:00
<i>Monday, January 30, 2012</i>				
	McLaughlin, Brad	7018 Tee Overhead	18:00	21:00
	Coats, Mike	6010/7018 4G, Open Root 3/8"	17:45	20:30
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	21:00
	Strom, Steven	6010/7018 6" Sch 80 5G	18:00	21:00
	Clark, Zach	6010/7018 6" Sch 80 2G	17:30	21:00
	Ervin, Caleb	6010 Tee Horiz	17:30	19:25
<i>Tuesday, January 31, 2012</i>				
	McLaughlin, Brad	7018 Tee Overhead	18:00	19:30
	McLaughlin, Brad	7018, Simulated Groove Weld with Flat Bars, overhead	19:30	21:00
	Coats, Mike	6010/7018 4G, Open Root 3/8"	17:30	18:00
	Coats, Mike	Simulated 5F Pipe	18:00	20:00
	Strom, Steven	6010/7018 6" Sch 80 5G	17:30	21:00
	Clark, Zach	6010/7018 6" Sch 80 2G	16:30	17:30
	Clark, Zach	6010/7018 6" Sch 80 6G	17:30	21:00
<i>Thursday, February 02, 2012</i>				
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	20:30
	McElwain, James	6010/7018 6" Sch 80 5G	16:30	20:30
<i>Monday, February 06, 2012</i>				
	McLaughlin, Brad	7018, Simulated Groove Weld with Flat Bars, overhead	18:00	19:30
	Coats, Mike	6010/7018 4G, Open Root 3/8"	18:00	20:00
	Hester, Michael	6010/7018 4G, Open Root 3/8"	16:30	20:30
	Strom, Steven	6010/7018 6" Sch 80 5G	17:30	20:30
	Clark, Zach	6010/7018 6" Sch 80 6G	17:00	19:00
	Ervin, Caleb	6010 Tee Vertical	16:30	19:20

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, February 07, 2012</i>				
	McLaughlin, Brad	7018, Simulated Groove Weld with Flat Bars, overhead	18:17	20:45
	Coats, Mike	6010/7018 4G, Open Root 3/8"	17:15	18:45
	Coats, Mike	Simulated 5F Pipe	18:45	20:15
	Hester, Michael	6010/7018 4G, Open Root 3/8"	16:30	21:00
	Strom, Steven	6010/7018 6" Sch 80 5G	18:00	21:00
	Ervin, Caleb	6010 Tee Vertical	17:00	20:00
<i>Thursday, February 09, 2012</i>				
	McLaughlin, Brad	7018, Simulated Groove Weld with Flat Bars, overhead	18:13	20:30
	Coats, Mike	Simulated 5F Pipe	16:30	20:00
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	20:30
	McElwain, James	6010/7018 6" Sch 80 5G	16:30	20:15
<i>Monday, February 13, 2012</i>				
	Coats, Mike	Simulated 5F Pipe	16:30	19:00
	Coats, Mike	6010/7018 6" Sch 80 5G	19:00	21:00
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	20:00
	McElwain, James	6010/7018 6" Sch 80 5G	16:30	20:25
	Strom, Steven	6010/7018 6" Sch 80 5G	17:15	20:30
	Ervin, Caleb	6010 Tee Vertical	17:00	18:30
	Ervin, Caleb	7018 Tee Horiz	18:30	19:00
	Ervin, Caleb	7018 Tee Vertical	19:00	20:00
	Borden,Bobby	7018 Tee Vertical	17:45	18:30
	Borden,Bobby	7018 Tee Overhead	18:30	20:00
	Borden,Bobby	6010 Butt Square Groove Open Root 3/16" Vertical	20:00	20:30
	Sadowski, Michael	7018 Tee Vertical	16:30	19:00
	Sadowski, Michael	7018 Tee Overhead	19:00	20:00
	Sadowski, Michael	6010 Butt Square Groove Open Root 3/16" Vertical	20:00	20:30

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Thursday, February 16, 2012</i>				
	McLaughlin, Brad	7018, Simulated Groove Weld with Flat Bars, overhead	18:00	19:30
	McLaughlin, Brad	Basic Welding Related Terms	19:30	20:30
	Coats, Mike	6010/7018 6" Sch 80 5G	17:00	19:30
	Coats, Mike	Basic Welding Related Terms	19:30	20:30
	Coats, Mike	Basic Welding Related Terms	19:30	19:30
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	19:30
	Hester, Michael	Basic Welding Related Terms	19:30	20:30
	McElwain, James	6010/7018 6" Sch 80 6G	17:40	19:30
	McElwain, James	Basic Welding Related Terms	19:30	20:35
	Strom, Steven	6010/7018 6" Sch 80 6G	17:30	19:30
	Strom, Steven	Basic Welding Related Terms	19:30	20:30
	Ervin, Caleb	7018 Tee Vertical	17:10	19:30
	Sadowski, Michael	Test 7018 3G	16:30	19:30
	Sadowski, Michael	Basic Welding Related Terms	19:30	20:30
	Johnson, CW	Test 7018 4G	17:45	19:30
	Johnson, CW	Basic Welding Related Terms	19:30	20:30
<i>Monday, February 20, 2012</i>				
	Hester, Michael	6010/7018 6" Sch 80 2G	17:00	20:00
	Strom, Steven	6010/7018 6" Sch 80 6G	18:00	20:30
	Ervin, Caleb	7018 Tee Vertical	17:30	20:00
	Sadowski, Michael	6010 Butt Square Groove Open Root 3/16" Vertical	17:00	20:00
<i>Tuesday, February 21, 2012</i>				
	Coats, Mike	6010/7018 3G, Open Root 3/8"	17:00	18:00
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	21:00
	McElwain, James	6010/7018 6" Sch 80 5G	16:30	21:00
	Strom, Steven	6010/7018 6" Sch 80 2G	16:30	21:00
	Clark, Zach	6010/7018 6" Sch 80 6G	16:30	21:00
<i>Thursday, February 23, 2012</i>				
	Hester, Michael	6010/7018 6" Sch 80 2G	16:00	20:30
	Strom, Steven	6010/7018 6" Sch 80 2G	18:00	20:30
	Clark, Zach	6010/7018 6" Sch 80 6G	16:30	19:30
	Clark, Zach	GTAW Tee, Fillet, Horizontal	19:30	20:00
	Clark, Zach	GTAW Tee, Fillet, Horizontal	20:00	21:00
	Ervin, Caleb	7018 Tee Vertical	18:00	20:00
<i>Monday, February 27, 2012</i>				
	Coats, Mike	6010/7018 2G, Open Root 3/8"	16:30	18:30
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	21:00
	McElwain, James	6010/7018 6" Sch 80 5G	16:30	20:00
	Strom, Steven	6010/7018 6" Sch 80 5G	17:30	21:00
	Sadowski, Michael	6010 Butt Square Groove Open Root 3/16" Vertical	16:30	19:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, February 28, 2012</i>				
	Coats, Mike	6010/7018 4G, Open Root 3/8"	16:30	19:00
	Hester, Michael	6010/7018 6" Sch 80 2G	16:30	21:00
	Strom, Steven	6010/7018 6" Sch 80 5G	17:30	21:00
	Ervin, Caleb	7018 Tee Vertical	17:30	20:00
	Sadowski, Michael	6010 Butt Square Groove Open Root 3/16" Overhead	16:30	20:00
<i>Monday, March 05, 2012</i>				
	Hester, Michael	FCAW 2 Tee Horiz	16:30	20:30
	Strom, Steven	6010/7018 6" Sch 80 5G	16:30	17:30
	Ervin, Caleb	7018 Tee Overhead	16:30	20:30
	Sadowski, Michael	6010 Butt Square Groove Open Root 3/16" Overhead	16:30	20:30
	Johnson, CW	6010 Tee Open Root vertical up	16:30	19:00
<i>Thursday, March 08, 2012</i>				
	Hester, Michael	6010/7018 3G, Open Root 3/8"	16:30	20:45
	Ervin, Caleb	7018 Tee Overhead	17:00	21:00
	Sadowski, Michael	6010 Butt Square Groove Open Root 3/16" Overhead	16:30	21:00
	Johnson, CW	6010 Tee Open Root vertical up	17:00	21:00
	Bowling, Blake	6010 Pad Weld Flat	16:30	20:45
	Nick, Davis	6010 Pad Weld Flat	16:30	20:45
	Micah, Vandiver	6010 Pad Weld Flat	17:00	21:00
<i>Monday, March 26, 2012</i>				
	McLaughlin, Brad	7018, Simulated Groove Weld with Flat Bars, overhead	16:30	20:49
	Hester, Michael	6010/7018 3G, Open Root 3/8"	16:30	20:45
	Strom, Steven	FCAW 7 Vertical 3G	17:00	21:00
	Ervin, Caleb	7018 Tee Overhead	17:15	20:15
	Bowling, Blake	6010 Pad Weld Flat	16:30	18:50
	Nick, Davis	6010 Pad Weld Flat	16:30	18:50
<i>Thursday, March 29, 2012</i>				
	Hester, Michael	FCAW 2 Tee Horiz	16:30	21:00
	Strom, Steven	FCAW 7 Vertical 3G	17:00	21:00
	Ervin, Caleb	7018 Pad Flat	17:00	18:30
	Ervin, Caleb	7018 Tee Overhead	18:30	20:00
	Sadowski, Michael	6010 Butt Square Groove Open Root 3/16" Overhead	17:00	19:30
<i>Monday, April 23, 2012</i>				
	Hester, Michael	FCAW 4 Tee Vertical	16:30	21:00
	Strom, Steven	FCAW 7 Vertical 3G	17:00	20:45
	Ervin, Caleb	7018 Tee Vertical	17:00	20:20
	Bowling, Blake	6010 Pad Weld Flat	16:30	20:53

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Monday, April 30, 2012</i>				
	Hester, Michael	FCAW 4 Tee Vertical	16:30	20:45
	Ervin, Caleb	7018 Tee Vertical	17:30	19:30
	Ervin, Caleb	7018 Tee Overhead	19:30	20:30
	Bowling, Blake	6010 Pad Weld Horiz	16:30	19:00
	Bowling, Blake	7018 Pad Flat	19:00	20:30
	Nick, Davis	FCAW 2 Tee Horiz	16:30	19:30
<i>Thursday, May 03, 2012</i>				
	Hester, Michael	FCAW 4 Tee Vertical	16:30	18:30
	Hester, Michael	FCAW 7 Tee Ovhd	18:30	20:30
	Bowling, Blake	6010 Pad Weld Horiz	16:30	20:30
	Nick, Davis	FCAW 1 Pad Flat	16:30	20:30
<i>Monday, May 07, 2012</i>				
	Hester, Michael	FCAW 4 Tee Vertical	16:30	18:00
	Hester, Michael	FCAW 7 Tee Ovhd	18:00	20:00
	Strom, Steven	FCAW 7 Vertical 3G	17:30	20:00
	Bowling, Blake	7018 Pad Vertical	16:30	19:55
	Nick, Davis	FCAW 2 Tee Horiz	16:30	20:00
<i>Thursday, May 10, 2012</i>				
	Hester, Michael	FCAW 4 Tee Vertical	17:30	18:00
	Hester, Michael	FCAW 7 Tee Ovhd	18:00	19:00
	Hester, Michael	FCAW 8 Ovhd 4G	19:00	19:45
	Hester, Michael	FCAW 7 Vertical 3G	19:45	21:00
	Strom, Steven	FCAW 7 Vertical 3G	17:30	21:00
	Nick, Davis	FCAW 2 Tee Horiz	16:30	21:00
<i>Monday, May 14, 2012</i>				
	Hester, Michael	FCAW 7 Vertical 3G	16:30	21:00
	Bowling, Blake	FCAW 1 Pad Flat	16:30	20:21
	Nick, Davis	FCAW 2 Tee Horiz	16:30	21:00
<i>Thursday, May 17, 2012</i>				
	Hester, Michael	FCAW 1 Pad Flat	16:30	19:00
	Strom, Steven	GMAW 3 Tee Horiz	16:30	20:30
<i>Monday, May 21, 2012</i>				
	Hester, Michael	FCAW 8 Ovhd 4G	16:30	21:00
	Bowling, Blake	FCAW 1 Pad Flat	16:30	17:45
	Bowling, Blake	7018 Pad Flat	17:45	21:00
	Nick, Davis	FCAW 2 Tee Horiz	16:30	18:00
	Nick, Davis	FCAW 2.1 Simulated vee Groove Flat	18:00	21:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Thursday, May 24, 2012</i>				
	Hester, Michael	FCAW 8 Ovhd 4G	16:30	19:00
	Hester, Michael	FCAW 7 Vertical 3G	19:00	19:45
	Nick, Davis	FCAW 2 Tee Horiz	16:30	17:00
	Nick, Davis	FCAW 2.1 Simulated vee Groove Flat	17:00	19:30
<i>Monday, May 28, 2012</i>				
	Hester, Michael	FCAW 7 Vertical 3G	16:30	18:00
	Hester, Michael	FCAW 8 Ovhd 4G	18:00	20:45
	Bowling, Blake	7018 Tee Horiz	16:30	20:00
	Nick, Davis	FCAW 2 Tee Horiz	16:30	17:00
	Nick, Davis	FCAW 3 Pad Vertical	17:00	20:00
<i>Tuesday, August 07, 2012</i>				
	Bowling, Blake	6010 Pad Weld Flat	16:00	20:30
	Elrod, Drake	6010 Pad Weld Flat	16:00	20:00
	Brashier, Chris	6010 Pad Weld Flat	16:00	20:30
	Hall, Jamie	6010 Pad Weld Flat	16:00	20:00
<i>Thursday, August 09, 2012</i>				
	Bowling, Blake	6010 Pad Weld Flat	16:00	20:00
	Elrod, Drake	6010 Pad Weld Flat	16:00	20:30
	Brashier, Chris	6010 Pad Weld Flat	16:00	20:30
	Hall, Jamie	6010 Pad Weld Flat	16:00	19:30
	Brown, Brian	6010 Pad Weld Flat	16:00	20:30
<i>Tuesday, August 14, 2012</i>				
	Bowling, Blake	6010 Pad Weld Flat	16:00	17:00
	Bowling, Blake	7018 Pad Flat	17:00	20:30
	Elrod, Drake	6010 Pad Weld Flat	16:00	17:00
	Elrod, Drake	7018 Pad Flat	17:00	19:00
	Brashier, Chris	6010 Pad Weld Flat	16:00	20:30
<i>Thursday, August 16, 2012</i>				
	Bowling, Blake	6010 Pad Weld Flat	16:00	17:00
	Bowling, Blake	7018 Pad Flat	17:00	19:30
<i>Tuesday, August 21, 2012</i>				
	Bowling, Blake	7018 Pad Flat	16:00	20:00
	Elrod, Drake	7018 Pad Flat	16:00	19:45
	Brashier, Chris	7018 Pad Flat	16:00	19:45
<i>Thursday, August 23, 2012</i>				
	Bowling, Blake	7018 Pad Flat	16:00	19:45
	Elrod, Drake	7018 Pad Vertical	16:00	20:00
	Brown, Donald	7018 Pad Vertical	18:30	20:30
<i>Tuesday, August 28, 2012</i>				
	Bowling, Blake	7018 Pad Horiz	16:00	19:35
	Elrod, Drake	7018 Pad Vertical	16:00	18:45

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Thursday, August 30, 2012</i>				
	Bowling, Blake	FCAW 4 Tee Vertical	16:00	19:30
	Plunk, Johnny	6010 Tee Horiz	16:00	20:00
	Brown, Donald	7018 Tee Horiz	16:05	20:30
<i>Tuesday, September 04, 2012</i>				
	Plunk, Johnny	FCAW 1 Pad Flat	16:00	18:00
	Plunk, Johnny	FCAW 3 Pad Vertical	18:00	20:15
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, overhead	16:05	20:30
<i>Thursday, September 06, 2012</i>				
	Bowling, Blake	FCAW 4 Tee Vertical	17:00	19:47
	Anglin, Perry	6010/7018 3G, Open Root 3/8"	17:00	20:00
	Plunk, Johnny	FCAW 4 Tee Vertical	17:00	20:00
	King, Gene	6010 Pad Weld Flat	17:00	18:00
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, overhead	17:00	20:00
<i>Tuesday, September 11, 2012</i>				
	Bowling, Blake	FCAW 4 Tee Vertical	16:00	17:41
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, overhead	16:00	18:00
<i>Thursday, September 13, 2012</i>				
	Bowling, Blake	FCAW 4 Tee Vertical	16:00	19:45
	Plunk, Johnny	FCAW Tee Vertical On Floor	16:00	19:00
	Plunk, Johnny	FCAW Tee Ovhd Under Table	19:00	20:30
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, overhead	16:00	20:00
<i>Tuesday, September 18, 2012</i>				
	Bowling, Blake	FCAW 2.1 Simulated vee Groove Flat	16:00	19:30
	Kay, Josh	Test 7018 3G	16:00	18:30
	Anglin, Perry	6010/7018 6" Sch 80 2G	16:30	19:00
<i>Thursday, September 20, 2012</i>				
	Bowling, Blake	7018 Tee Horiz	16:00	19:00
	Kay, Josh	Test 7018 3G	16:40	19:30
	Brown, Donald	7018 Pad Overhead	16:15	20:15

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, September 25, 2012</i>				
	Bowling, Blake	7018 Tee Horiz	16:00	19:00
	Plunk, Johnny	FCAW Tee Vertical On Floor	16:00	18:45
	Plunk, Johnny	FCAW 2.1 Simulated vee Groove Flat	16:30	20:30
	Plunk, Johnny	FCAW Tee Ovhd Under Table	18:45	20:45
	Hernandez, Wilson	6010 Pad Weld Flat	17:00	18:00
	Hernandez, Wilson	6010 Pad Weld Horiz	18:00	18:30
	Hernandez, Wilson	6010 Pad Weld Vertical.	18:30	19:00
	Hernandez, Wilson	6010 Tee Vertical	19:00	19:30
	Grisham, Shawn	7018 Tee Vertical	17:15	20:15
	Taylor, Ryan	FCAW 1 Pad Flat	16:30	20:30
	Yarbrough, Gerald	6010 Pad Weld Flat	17:00	20:30
	McCameron, Andrew	6010 Pad Weld Flat	17:00	20:30
<i>Thursday, September 27, 2012</i>				
	Kay, Josh	7018, Simulated Groove Weld with Flat Bars, Vertical	16:40	18:00
	Plunk, Johnny	FCAW 7 Vertical 3G	16:30	18:30
	Plunk, Johnny	FCAW 5 Lap Vert	18:30	20:30
	Hernandez, Wilson	6010 Pad Weld Flat	17:00	18:00
	Hernandez, Wilson	6010 Pad Weld Horiz	18:00	18:30
	Hernandez, Wilson	6010 Pad Weld Vertical.	18:30	19:00
	Hernandez, Wilson	6010 Tee Vertical	19:00	19:30
	Grisham, Shawn	7018 Tee Vertical	17:15	20:15
	Taylor, Ryan	FCAW 1 Pad Flat	16:30	20:30
	Yarbrough, Gerald	6010 Pad Weld Flat	17:00	20:30
	McCameron, Andrew	Safety Issues	20:00	20:30
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:30	18:00
<i>Tuesday, October 02, 2012</i>				
	Kay, Josh	7018, Simulated Groove Weld with Flat Bars, Vertical	16:40	20:00
	Grisham, Shawn	7018 Tee Vertical	17:10	20:30
<i>Thursday, October 04, 2012</i>				
	Bowling, Blake	FCAW 1 Pad Flat	16:00	18:50
	Grisham, Shawn	GTAW 1 Push a Puddle Flat on 3/16" Plate	17:00	20:40
	Toro, Erik	6010 Pad Weld Flat	17:30	20:30
	Toro, Jesus	6010 Pad Weld Flat	17:30	20:30
	Welch, William	6010 Pad Weld Flat	17:00	19:00
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:00	19:45

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, October 09, 2012</i>				
	Bowling, Blake	7018 Tee Horiz	16:00	20:00
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Vertical	16:55	20:55
	Yarbrough, Gerald	6010 Pad Weld Flat	17:40	20:30
	McCameron, Andrew	6010 Pad Weld Flat	17:40	20:30
	Toro, Erik	6010 Pad Weld Flat	17:30	20:30
	Toro, Jesus	6010 Pad Weld Flat	17:30	20:30
	Keller, Troy	6010 Pad Weld Flat	16:20	17:30
	Castleberry, John	6010 Pad Weld Flat	17:00	20:09
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:30	19:30
<i>Thursday, October 11, 2012</i>				
	Bowling, Blake	FCAW 4 Tee Vertical	16:20	18:00
	Bowling, Blake	7018 Tee Vertical	18:00	19:15
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Vertical	17:40	20:20
	Yarbrough, Gerald	6010 Pad Weld Flat	18:45	20:30
	McCameron, Andrew	6010 Pad Weld Flat	18:45	20:30
	Toro, Jesus	6010 Pad Weld Flat	17:15	20:30
	Castleberry, John	7018 Pad Flat	17:40	20:10
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:15	19:30
<i>Tuesday, October 16, 2012</i>				
	Bowling, Blake	FCAW Tee Vertical On Floor	16:12	20:30
	Plunk, Johnny	FCAW 4 Tee Vertical	16:30	17:30
	Plunk, Johnny	FCAW 5 Lap Vert	17:30	19:30
	Plunk, Johnny	FCAW Tee Vertical On Floor	19:30	20:30
	Grisham, Shawn	GTAW Tee, Fillet, Horizontal	17:30	19:00
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Vertical	19:00	20:00
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Overhead	20:00	20:50
	Toro, Erik	7018 Tee Horiz	17:25	20:12
	Toro, Jesus	6010 Tee Horiz	17:25	20:30
	Brown, Donald	7018 Tee Overhead	16:10	20:00
<i>Thursday, October 18, 2012</i>				
	Bowling, Blake	FCAW 4 Tee Vertical	16:00	17:55
	Grisham, Shawn	Test 7018 3G	18:00	20:45
	Yarbrough, Gerald	6010 Pad Weld Flat	18:20	20:20
	McCameron, Andrew	6010 Pad Weld Flat	18:20	20:20
	Brown, Donald	7018 Tee Vertical	16:00	18:45
	Brown, Donald	7018 Tee Overhead	18:45	19:45

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, October 23, 2012</i>				
	Bowling, Blake	7018 Tee Vertical	16:10	17:00
	Bowling, Blake	FCAW 4 Tee Vertical	17:00	17:45
	Bowling, Blake	FCAW 7 Tee Ovhd	17:45	18:20
	Brown, Brian	7018 Tee Overhead	16:00	18:30
	Grisham, Shawn	FCAW Tee Ovhd Under Table	16:40	17:40
	Grisham, Shawn	FCAW Tee Vertical On Floor	17:40	18:00
	Grisham, Shawn	GTAW 3 Run 1" Long Horizontal bead pad weld.	18:00	20:00
	Yarbrough, Gerald	6010 Pad Weld Flat	18:30	20:30
	McCameron, Andrew	6010 Pad Weld Flat	18:30	20:30
	Toro, Erik	7018 Tee Horiz	17:15	20:30
	Toro, Jesus	6010 Pad Weld Flat	17:15	18:00
	Toro, Jesus	7018 Pad Flat	18:00	18:45
	Toro, Jesus	7018 Pad Vertical	18:45	20:30
<i>Thursday, October 25, 2012</i>				
	Grisham, Shawn	GMAW 11 Butt Vert Open Root	17:30	18:40
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Vertical	18:40	19:40
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Overhead	19:40	20:30
	Yarbrough, Gerald	6010 Pad Weld Horiz	18:30	20:30
	McCameron, Andrew	6010 Pad Weld Flat	18:30	20:30
	Toro, Jesus	7018 Pad Vertical	17:25	18:25
	Toro, Jesus	6010 Tee Horiz	18:25	20:30
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, overhead	16:00	20:00
<i>Tuesday, October 30, 2012</i>				
	Bowling, Blake	7018 Pad Vertical	16:30	18:00
	Bowling, Blake	FCAW 4 Tee Vertical	18:00	19:20
	Bowling, Blake	FCAW 7 Tee Ovhd	19:20	20:30
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Vertical	17:20	19:00
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Overhead	19:00	20:30
	Yarbrough, Gerald	6010 Pad Weld Horiz	18:20	20:30
	McCameron, Andrew	Safety Issues	18:20	20:30
	Toro, Erik	7018 Tee Horiz	17:30	20:30
	Toro, Jesus	7018 Tee Horiz	17:30	20:30
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:30	20:15
	Jagneki, Kirk	6010 Pad Weld Flat	17:30	18:00
	Jagneki, Kirk	6010 Pad Weld Horiz	18:00	20:30

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Thursday, November 01, 2012</i>				
	Bowling, Blake	FCAW 1 Pad Flat	16:00	18:15
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Vertical	17:20	20:35
	Grisham, Shawn	6010/7018 3G, Open Root 3/8"	19:00	20:30
	Yarbrough, Gerald	6010 Pad Weld Horiz	18:00	20:30
	McCameron, Andrew	6010 Pad Weld Flat	18:00	20:30
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:00	19:15
	Jagneki, Kirk	6010 Pad Weld Flat	16:00	20:30
<i>Tuesday, November 06, 2012</i>				
	Grisham, Shawn	FCAW 4 Tee Vertical	17:00	20:30
	Yarbrough, Gerald	6010 Pad Weld Horiz	17:54	20:30
	McCameron, Andrew	6010 Pad Weld Flat	17:54	20:30
	McCameron, Andrew	6010 Pad Weld Flat	18:00	20:30
	Toro, Jesus	7018 Tee Horiz	17:15	20:30
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:00	19:45
	Jagneki, Kirk	6010 Pad Weld Horiz	16:15	20:30
<i>Thursday, November 08, 2012</i>				
	Grisham, Shawn	FCAW 4 Tee Vertical	17:50	19:00
	Grisham, Shawn	FCAW 7 Tee Ovhd	19:00	20:30
	Yarbrough, Gerald	6010 Pad Weld Horiz	18:00	20:30
	Toro, Erik	7018 Tee Horiz	17:40	20:18
	Toro, Jesus	7018 Tee Horiz	17:40	20:30
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:00	19:30
	Jagneki, Kirk	6010 Pad Weld Vertical.	16:30	20:30
<i>Tuesday, November 13, 2012</i>				
	Bowling, Blake	7018 Tee Vertical	16:00	18:00
	Bowling, Blake	FCAW 4 Tee Vertical	18:00	19:15
	Grisham, Shawn	FCAW 4 Tee Vertical	18:00	18:45
	Grisham, Shawn	6010 Butt Square Groove Open Root 3/16" Vertical	18:45	19:30
	Toro, Jesus	7018 Tee Horiz	17:45	20:30
	Jagneki, Kirk	6010 Pad Weld Vertical.	16:30	20:30
<i>Thursday, November 15, 2012</i>				
	Bowling, Blake	7018 Pad Overhead	16:00	20:30
	Yarbrough, Gerald	6010 Pad Weld Vertical.	18:00	20:30
	McCameron, Andrew	6010 Pad Weld Flat	18:00	20:30
	Toro, Erik	6010 Pad Weld Vertical.	17:30	19:00
	Toro, Erik	7018 Pad Vertical	19:00	20:30
	Toro, Jesus	FCAW 1 Pad Flat	17:30	20:30
	Brown, Donald	7018 Tee Vertical	16:00	19:30
	Jagneki, Kirk	6010 Pad Weld Vertical.	18:00	20:30
	Jones, Davey	FCAW Tee Vertical On Floor	17:00	18:30
	Jones, Davey	FCAW Tee Ovhd Under Table	18:30	19:45

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, November 20, 2012</i>				
	Clark, Zach	6010 Butt Square Groove Open Root 3/16" Vertical	16:00	19:06
	Bowling, Blake	FCAW 3 Pad Vertical	16:00	19:00
	Yarbrough, Gerald	6010 Pad Weld Flat	17:50	20:30
	McCameron, Andrew	6010 Pad Weld Flat	17:50	20:30
<i>Tuesday, November 27, 2012</i>				
	Bowling, Blake	7018 Tee Vertical	16:00	18:30
	Yarbrough, Gerald	6010 Pad Weld Flat	18:00	20:17
	McCameron, Andrew	6010 Pad Weld Flat	18:00	19:00
	McCameron, Andrew	6010 Pad Weld Horiz	19:00	20:17
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:00	19:10
	Jagneki, Kirk	6010 Tee Horiz	16:45	20:15
	Sanderson, Bradley	6010 Pad Weld Flat	16:45	18:15
<i>Thursday, November 29, 2012</i>				
	Bowling, Blake	Ch 3 and Complete Welding Symbols Quiz Open Book	16:00	18:00
	Yarbrough, Gerald	6010 Pad Weld Vertical.	18:15	20:15
	McCameron, Andrew	6010 Pad Weld Flat	18:15	20:15
	Jagneki, Kirk	Ch 3 and Complete Welding Symbols Quiz Open Book	16:15	19:00
<i>Tuesday, December 04, 2012</i>				
	Grisham, Shawn	7018 Tee Vertical	17:30	20:45
	Yarbrough, Gerald	6010 Tee Horiz	17:45	20:45
	McCameron, Andrew	6010 Pad Weld Flat	17:45	20:45
	Brown, Donald	Test 7018 3G	16:00	20:00
	Jagneki, Kirk	6010 Tee Horiz	16:45	20:15
<i>Thursday, December 06, 2012</i>				
	Bowling, Blake	7018 Tee Vertical	16:00	19:30
	Bowling, Blake	FCAW 4 Tee Vertical	19:30	20:30
	Grisham, Shawn	GMAW 1 Setup and Flat Pad Weld	18:30	20:30
	Yarbrough, Gerald	6010 Tee Horiz	18:00	20:20
	McCameron, Andrew	6010 Pad Weld Flat	18:00	20:20
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:00	19:00
	Thomas, Ian	6010 Pad Weld Flat	16:00	20:30
	Jones, Davey	FCAW Tee Vertical On Floor	18:00	20:30
	Richardson, Cody	6010 Pad Weld Flat	16:00	20:30

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, December 11, 2012</i>				
	Bowling, Blake	7018 Tee Vertical	16:00	17:00
	Bowling, Blake	FCAW 4 Tee Vertical	17:00	18:00
	Bowling, Blake	FCAW 7 Tee Ovhd	18:00	19:10
	Grisham, Shawn	GTAW 3 Run 1" Long Horizontal bead pad weld.	19:00	20:30
	Yarbrough, Gerald	6010 Tee Horiz	18:00	20:12
	McCameron, Andrew	6010 Pad Weld Flat	18:00	20:30
	Jagneki, Kirk	6010 Tee Horiz	16:15	20:05
	Thomas, Ian	6010 Pad Weld Flat	16:00	20:15
	Jones, Davey	FCAW Tee Vertical On Floor	17:10	20:15
<i>Thursday, December 13, 2012</i>				
	Bowling, Blake	7018 Pad Overhead	16:00	19:30
	Grisham, Shawn	GTAW 2 Flat Run a 3" bead adding Filler Metal walking over wire. No dipping.	18:00	19:30
	Brown, Donald	7018, Simulated Groove Weld with Flat Bars, Vertical	16:00	19:00
	Thomas, Ian	6010 Pad Weld Flat	16:00	19:30
<i>Tuesday, December 18, 2012</i>				
	Bowling, Blake	7018 Pad Overhead	16:00	20:30
	Grisham, Shawn	GTAW 1 Push a Puddle Flat on 3/16" Plate	19:00	19:45
	Grisham, Shawn	GMAW 3 Tee Horiz	19:45	20:35
	Yarbrough, Gerald	6010 Pad Weld Flat	18:00	20:20
	McCameron, Andrew	6010 Pad Weld Flat	18:00	20:20
	Jagneki, Kirk	6010 Tee Horiz	17:15	20:30
	Thomas, Ian	6010 Pad Weld Flat	16:00	18:00
	Thomas, Ian	6010 Pad Weld Flat	16:00	18:20
	Thomas, Ian	6010 Pad Weld Horiz	18:00	19:30
	Thomas, Ian	6010 Pad Weld Horiz	18:20	20:20
	Jones, Davey	FCAW Tee Vertical On Floor	16:45	18:45
<i>Thursday, December 20, 2012</i>				
	Bowling, Blake	7018 Tee Vertical	16:00	20:30
	Grisham, Shawn	GTAW 1 Push a Puddle Flat on 3/16" Plate	17:00	20:35
	McCameron, Andrew	6010 Pad Weld Flat	17:55	20:20
	Brown, Donald	7018 Tee Vertical	16:30	20:20
	Jagneki, Kirk	6010 Pad Weld Flat	16:20	18:20
	Jagneki, Kirk	6010 Tee Horiz	18:20	20:20
	Thomas, Ian	6010 Pad Weld Flat	16:15	18:30
	Thomas, Ian	6010 Pad Weld Horiz	18:30	20:30
<i>Monday, December 24, 2012</i>				
	Bowling, Blake	FCAW 2 Tee Horiz	10:00	13:00
	Thomas, Ian	FCAW 1 Pad Flat	10:00	13:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Wednesday, December 26, 20</i>				
	Bowling, Blake	7018 Tee Horiz	16:00	19:30
	Grisham, Shawn	GMAW 1 Setup and Flat Pad Weld	19:15	20:15
	Thomas, Ian	7018 Tee Horiz	16:00	19:40
<i>Tuesday, January 01, 2013</i>				
	Bowling, Blake	7018 Tee Overhead	16:00	19:45
	Yarbrough, Gerald	7018 Pad Vertical	18:15	19:55
	Thomas, Ian	6010 Pad Weld Vertical.	16:00	17:00
	Thomas, Ian	7018 Pad Vertical	17:00	19:55
<i>Thursday, January 03, 2013</i>				
	Bowling, Blake	7018 Pad Vertical	16:00	20:15
	Yarbrough, Gerald	6010 Pad Weld Flat	18:45	20:15
	Thomas, Ian	6010 Pad Weld Vertical.	18:00	19:00
	Thomas, Ian	7018 Pad Vertical	19:00	19:30
	Thomas, Ian	6010 Pad Weld Overhead.	19:30	20:00
	Thomas, Ian	7018 Pad Overhead	20:00	20:30
	Lamber, Thomas	GTAW 3 Run 1" Long Horizontal bead pad weld.	16:00	20:30
<i>Tuesday, January 08, 2013</i>				
	Bowling, Blake	7018 Pad Vertical	16:00	18:30
	Thomas, Ian	6010 Pad Weld Overhead.	16:00	17:30
	Thomas, Ian	7018 Pad Overhead	17:30	18:30
	Lamber, Thomas	GTAW 1 Push a Puddle Flat on 3/16" Plate	16:00	18:30
<i>Thursday, January 10, 2013</i>				
	Bowling, Blake	FCAW 1 Pad Flat	16:00	19:15
	Yarbrough, Gerald	7018 Pad Flat	18:30	20:15
	Thomas, Ian	7018 Tee Horiz	16:00	20:15
	Lamber, Thomas	GTAW 1 Push a Puddle Flat on 3/16" Plate	16:00	20:15
<i>Thursday, January 17, 2013</i>				
	Bowling, Blake	7018 Tee Vertical	16:00	19:15
	Grisham, Shawn	GTAW 1 Push a Puddle Flat on 3/16" Plate	18:00	19:50
	Thomas, Ian	7018 Tee Vertical	16:00	19:50
	Devine, Tommy	Ch 1 and Complete General Shop Safety Quiz Open Book	16:00	19:50
	Little, Jeremy	Ch 1 and Complete General Shop Safety Quiz Open Book	16:00	19:50
	Phillips, Jeffrey	6010 Pad Weld Flat	16:00	20:00
<i>Tuesday, January 22, 2013</i>				
	Bowling, Blake	7018 Tee Overhead	16:00	18:00
	Grisham, Shawn	FCAW 7 Vertical 3G	18:00	20:30
	Yarbrough, Gerald	6010 Pad Weld Flat	18:00	20:30
	Thomas, Ian	7018 Tee Vertical	16:00	18:00
	Devine, Tommy	Ch 2 and Complete Print Reading Quiz Open Book	16:00	20:00
	Little, Jeremy	Ch 2 and Complete Print Reading Quiz Open Book	16:00	20:00
	Phillips, Jeffrey	6010 Pad Weld Flat	18:00	20:00

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Thursday, January 24, 2013</i>				
	Bowling, Blake	GMAW 1 Setup and Flat Pad Weld	16:00	17:45
	Bowling, Blake	GMAW 3 Tee Horiz	17:45	20:00
	Thomas, Ian	7018 Tee Vertical	16:00	19:00
	Thomas, Ian	7018 Tee Overhead	19:00	20:10
	Devine, Tommy	6010 Pad Weld Flat	16:00	20:15
	Little, Jeremy	6010 Pad Weld Flat	16:00	20:15
<i>Tuesday, January 29, 2013</i>				
	Bowling, Blake	GMAW 1 Setup and Flat Pad Weld	16:00	17:50
	Thomas, Ian	7018 Tee Vertical	17:45	20:00
	Austin, Gabriel	FCAW 1 Pad Flat	16:15	18:25
<i>Thursday, January 31, 2013</i>				
	Bowling, Blake	GMAW 2 Setup and Horiz Pad Weld	17:00	18:15
	Yarbrough, Gerald	GMAW 1 Setup and Flat Pad Weld	17:41	17:53
	Thomas, Ian	7018 Tee Vertical	17:00	18:15
	Devine, Tommy	6010 Pad Weld Flat	17:00	20:15
	Little, Jeremy	6010 Pad Weld Flat	17:00	20:15
	Austin, Gabriel	GMAW 2 Setup and Horiz Pad Weld	17:00	20:15
<i>Tuesday, February 05, 2013</i>				
	Yarbrough, Gerald	7018 Pad Horiz	18:00	20:15
	Thomas, Ian	7018 Tee Vertical	16:00	18:30
	Devine, Tommy	6010 Pad Weld Flat	17:30	20:15
	Little, Jeremy	6010 Pad Weld Flat	16:00	20:15
	Lamber, Thomas	GTAW 1 Push a Puddle Flat on 3/16" Plate	17:30	20:30
<i>Thursday, February 07, 2013</i>				
	Bowling, Blake	FCAW 3 Pad Vertical	16:00	17:30
	Yarbrough, Gerald	7018 Pad Horiz	18:10	20:30
	Jagneki, Kirk	GMAW 1 Setup and Flat Pad Weld	17:30	20:15
	Thomas, Ian	7018 Tee Vertical	16:00	18:30
	Devine, Tommy	6010 Pad Weld Flat	16:00	20:15
	Little, Jeremy	6010 Pad Weld Flat	16:00	20:15
	Lamber, Thomas	GTAW 3 Run 1" Long Horizontal bead pad weld.	18:10	20:35
<i>Tuesday, February 12, 2013</i>				
	Bowling, Blake	7018 Tee Vertical	16:00	17:40
	Yarbrough, Gerald	7018 Pad Horiz	18:05	19:06
	Thomas, Ian	7018 Tee Vertical	16:00	17:40
	Devine, Tommy	6010 Pad Weld Horiz	16:00	17:40
	Lamber, Thomas	GTAW 1 Push a Puddle Flat on 3/16" Plate	18:15	18:16

<i>Date</i>	<i>Student</i>	<i>Worked On</i>	<i>Start</i>	<i>Stop</i>
<i>Tuesday, February 19, 2013</i>				
	Bowling, Blake	7018 Tee Vertical	16:45	17:57
	Thomas, Ian	7018 Tee Vertical	16:00	18:30
	Devine, Tommy	7018 Pad Flat	16:00	19:45
	Little, Jeremy	6010 Pad Weld Horiz	16:00	19:45
	Lamber, Thomas	GTAW 2 Flat Run a 3" bead adding Filler Metal walking over wire. No dipping.	16:30	17:30
	Austin, Gabriel	GTAW 2 Flat Run a 3" bead adding Filler Metal walking over wire. No dipping.	16:00	19:30
<i>Tuesday, February 26, 2013</i>				
	Yarbrough, Gerald	7018 Pad Horiz	18:00	20:30
	Thomas, Ian	7018 Tee Vertical	16:00	17:00
	Thomas, Ian	6010 Tee Vertical	17:00	18:00
	Devine, Tommy	FCAW 1 Pad Flat	16:00	17:45
	Devine, Tommy	FCAW 1.1 Pad Horiz	17:45	20:00
	Lamber, Thomas	GTAW 3 Run 1" Long Horizontal bead pad weld.	18:30	20:30
	Burcham, Donna	Ch 1 and Complete General Shop Safety Quiz Open Book	18:00	19:30
	Burcham, Donna	Ch 2 and Complete Print Reading Quiz Open Book	19:30	20:30
	Tigner, Tristan	FCAW 1 Pad Flat	16:00	16:45
	Tigner, Tristan	FCAW 1.1 Pad Horiz	16:45	17:30
	Tigner, Tristan	FCAW 1.2 Pad vert	17:30	18:15
	Tigner, Tristan	FCAW 2 Tee Horiz	18:15	20:30
<i>Thursday, February 28, 2013</i>				
	Yarbrough, Gerald	7018 Pad Horiz	18:30	20:30
	Thomas, Ian	7018 Tee Vertical	16:00	20:00
	Devine, Tommy	FCAW 1.3 Pad Horiz	16:30	20:15
	Little, Jeremy	6010 Pad Weld Horiz	16:30	20:15
	Austin, Gabriel	FCAW Tee Vertical On Floor	16:20	18:50
	Burcham, Donna	Ch 4 and Answer Quiz pp 96	16:15	17:30
	Burcham, Donna	6010 Pad Weld Flat	17:30	20:30
	Tigner, Tristan	FCAW 4 Tee Vertical	16:00	20:30
<i>Tuesday, March 05, 2013</i>				
	Bowling, Blake	7018, Simulated Groove Weld with Flat Bars, Vertical	16:00	18:15
	Thomas, Ian	7018, Simulated Groove Weld with Flat Bars, Vertical	16:00	20:30
	Devine, Tommy	FCAW 3 Pad Vertical	16:00	18:30
	Devine, Tommy	FCAW 6 Pad Ovhd	18:30	20:10
	Little, Jeremy	6010 Pad Weld Horiz	16:00	17:30
	Little, Jeremy	6010 Pad Weld Vertical.	17:30	20:10
<i>Thursday, March 07, 2013</i>				
	Thomas, Ian	7018 Pad Vertical	16:00	17:30
	Burcham, Donna	6010 Pad Weld Flat	16:00	20:30
	Tigner, Tristan	FCAW 2.1 Simulated vee Groove Flat	16:00	19:00