

This welding graduate has successfully completed the following procedures:

SMAW

3 G (Vertical)
4 G (Overhead)

GMAW

2 G (Horizontal)
3 G (Vertical) Pulse

GMAW: Fluxcore

3 G (Vertical)
4 G (Overhead)

GTAW

(TIG) – Intro to c/s, Alloys and c/s Pipe (6G)

Carbon Arc Gouge Training

Oxy/Fuel Torch Cutting

Weld Symbols