

# Contents

<b>1</b>	<b>Stainless steels .....</b>	<b>7</b>	<b>Edge preparation .....</b>	<b>83</b>	
	Ferritic steels 7 · Steel tables 9 · Martensitic and precipitation hardening steels 14 · Austenitic steels 15 · Austenitic-ferritic (duplex) steels 17 · The physical properties of stainless and mild steels 19 · The importance of ferrite 19		Choice of joint type 83 · Cleaning before welding 83 · Joint types (table) 84		
<b>2</b>	<b>Definitions .....</b>	<b>23</b>	<b>8</b>	<b>Shielding and backing gases .....</b>	<b>89</b>
	Welding positions 23 · Heat-affected zone 24 · Heat input 24 · Interpass temperature 24 · Penetration and dilution 25 · Metal deposition rate 25 · Post-weld heat treatment 25 · Effect of high silicon content 26 · Cast and helix 26		Shielding gas function 89 · Shielding gas components 89 · Backing gases 90 · MIG welding 91 · TIG welding 92 · FCAW 93 · PAW 93		
<b>3</b>	<b>Stainless steel welding methods .....</b>	<b>27</b>	<b>9</b>	<b>Post-weld cleaning of stainless steel .....</b>	<b>95</b>
	Welding terminology and abbreviations 27 · MMA welding 28 · The Vital Arc Concept 30 · MIG welding 31 · TIG welding 34 · SAW 35 · FCAW 37 · PAW 38 · Laser welding 39		Typical defects 95 · Cleaning procedures 96 · Mechanical methods 96 · Chemical methods 97 · Choice of method 99 · The Rainbow Concept 100		
<b>4</b>	<b>Welding techniques .....</b>	<b>41</b>	<b>10</b>	<b>Storage and handling recommendations for covered electrodes, flux-cored wire and fluxes .....</b>	<b>101</b>
	Fit-up and tack welding 41 · Planning the welding sequence 43 · Stringer beads versus weaving 45 · Vertical-up and vertical-down welding 45 · Backhand versus forehand welding 47 · Width and depth 47 · Distortion 48 · Welding stainless to mild steel 49 · Overlay welding 50 · Welding clad steel plates 54 · Repair welding 55		Storage 101 · Handling of open packages 101 · Handling of electrodes in the welding area 101 · Rebaking of electrodes and fluxes 101		
<b>5</b>	<b>Weld imperfections .....</b>	<b>57</b>	<b>11</b>	<b>Standards and approvals .....</b>	<b>103</b>
	Inspection 57 · Lack of fusion 58 · Incomplete penetration 59 · Solidification and liquation cracking 60 · Crater cracks 61 · Porosity 62 · Slag inclusions 63 · Spatter 64 · Undercut 65 · Stray arcing 66 · Burn-through 66 · Slag islands 67 · Excessive weld metal 67		EN standards 104 · AWS standards 108		
<b>6</b>	<b>Welding practice – Guidelines for welding different types of stainless steels .....</b>	<b>69</b>	<b>12</b>	<b>Recommended filler metals .....</b>	<b>113</b>
	Welding procedure design 69 · Austenitic Cr-Ni and Cr-Ni-Mo steels 71 · High-alloy austenitic steels 72 · Duplex steels 76 · High-temperature steels 78 · Ferritic, martensitic and precipitation hardening steels 80		Similar welding 113 · Dissimilar welding 113		
			<b>13</b>	<b>Filler metal and flux consumption .....</b>	<b>117</b>
			<b>14</b>	<b>Product data sheets .....</b>	<b>119</b>
				Covered electrodes 120 · MIG wire 185 · TIG wire 211 · SAW wire 241 · FCW 261 · Welding flux 275 · Finishing chemicals 279	
			<b>15</b>	<b>Packaging data .....</b>	<b>285</b>
				Conversion tables .....	287
				Abbreviations .....	289
				Index .....	291