


### Incomplete Welds



Welds not connected makes weld incomplete



Insufficient leg size makes weld incomplete



### Other Defects



Crack

Excessive spatter  
See FPR0904 and FPR0905



### Burn-through

