

Test Methods for EN ISO 9606 – 5 (Ti) test result validation:

Test Method	Butt Joint Plate	Butt Joint Tube	Fillet Weld
Visual Test*	Required	Required	Required
Bending Test	Required	Required	Required
Strain to Fracture	Not required	Not required	Required
PT	Not required	Not required	Not required
Hardness Test	Not required	Not required	Not required
Radiography	Not required	Not required	Not required

*An additional determination of oxide layers (colors) is required when visually testing the specimen.