



Left:
Measurement for the required throat for a $\frac{1}{4}$ " reinforcing fillet weld. Measurement indicated that **insufficient** throat existed (see arrow & gap to left).



Left:
Example of **acceptable** throat measurement for a $\frac{1}{4}$ " reinforcing fillet weld.