

## Laves-Phases:

Binary Silver (Ag) – Strontium (Sr) – phase diagram showing different stringent defined Laves-phases ( $\text{SrAg}_5$  –  $\text{Sr}_3\text{Ag}_5$  –  $\text{SrAg}$  –  $\text{Sr}_3\text{Ag}_2$ ).

