

B Lynchburg Steel

A B E T A C O M P A N Y

Rt. 29, North P.O. Box 158 Monroe, VA 24574 Phone: (434) 929-0951 Fax: (434) 929-2613
LYNCHBURG STEEL SOUTHERN STEEL CAROLINA REBAR
www.betainternational.com

Form QC-5

Mill Material Discrepancy Report

Date 11/11/2008

Project	<u>#08-010 Morgan Stanley</u>	Specification	<u>ASTM A992/572-50</u>
Section	<u>W14 x 120 x 27'-0</u>	Heat Number	<u>30439720</u>
Source	<u>Gerdau Ameristeel - Petersburg</u>	Mill Order Number	<u>PO#5036</u>
		Shop Order Number	<u>SO#7696</u>
		Piece Mark	<u>?? Sequence #15</u>

Description of Defect:

Column has damage to the flange.

Area of concern is @ 15'-1" thru 16'-0" from the end of the column.



Disposition - Mill Directive:

Note to Purchasing: Replaced with another W14 x 120 x 27'-0 off the same job.

CC: Purchasing
Production
Quality Control